

RISK ASSESSMENT

Company	Connex Scaffolding
Company Address	15/A Queensland Road, Boscombe, Bournemouth, BH5 2AB Tel: 0844 800 2407 Mobile: 078 34776947

Project	RD Leadwork Specialists
Project Address	Pending

Assessment Date	Review Date	Name of Assessor	Unique Reference
01/08/2007	01/02/2008	William Thomas Banks	RISK17_15_5_2007

Trade	Scaffolder
Activity	Scaffolding
Person(s) at Risk	General Operative Labourer

Health/Safety Hazard	Setting up Site/General Site Conditions
Risk Management	<ul style="list-style-type: none"> • The site boundary is clearly defined with access to site controlled • The site can be secured to prevent un-authorized out-of-hours access • Additional measures are taken to discourage trespass by children • The site office and site entrance are clearly marked • Appropriate signs are displayed at the site entrance and other places • The site is kept in a tidy condition • All employees are issued with appropriate PPE-safety boots, safety helmet and high-visibility waistcoat as a minimum • Appropriate first aid equipment is available
Residual risk-SEVERITY	LOW
Residual risk-LIKELIHOOD	LOW

Health/Safety Hazard	Lack of Communication, Information & Training
Risk Management	<ul style="list-style-type: none"> • All employees, sub-contractor and visitors undergo a Health and Safety induction on their first day on site • Sub-contractors provide Risk Assessment/Method Statements for their work • Staff have Risk Assessments/Method Statements explained to them